

GARY R. HERBERT

Governor

SPENCER J. COX

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA Division Director

Minerals Inspection Report

Reviewed

d P1915

Report Date: 04/21/2014 Mine Name: Pandora Mine Permit Number: M/037/0012 Mine Status: Active Operator Name: Energy Fuels Resources (USA) Inspection Date: 04/15/2014 Permit Fees: Paid Inspector(s): M. Bradley Inspection Time: 11:00a **Bond Amount:** \$175,811 Attendee(s): See below Weather: Pt. Cldy, cool **Bond Escalation:** 09/21/2015 Inspection Purpose: Routine inspection 06/13/2013 Prior Inspection:

Conclusions and Recommendations

UTM Location: Zone 12N, E655696m, N4241478m

Attendees: Becky Doolittle, BLM; Joe Manning, BLM; Andrea Reither, EFR; Stephen Downs, EFR; Race Fisher, EFR; Todd Eldredge, EFR. No significant changes since last inspection. Various scrap metal still on facilities pad. All mine equipment and vehicles stored on site had been emptied of fuel by thieves. Portal still sealed and secured. No erosion problems evident on site. No visible signs of eminent threats to public health and safety, or the environment.

	Elements of Inspection	Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds		
	Fees current, bond escalation due in September, 2015		
2.	Public Safety (shafts, adits, trash, signs, highwalls)		
	Portal remains sealed		
3.	Protection of Drainages/Erosion Control		
4.	Deleterious Material		
5.	Roads (maintenance, surfacing, dust control, safety)		
	Access road is somewhat rough and rutted.		
6.	Reclamation		
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)		
8.	Soils		
9.	Revegetation		
	Discussed areas that should have temporary revegetation seeding for temporar	ary suspension	San Barrier
10.	Other		

Inspector's Signature:

CC: Becky Doolittle, BLM (rdoolitt@blm.gov)
Andrea Reither, EFR (areither@energyfuels.com)
Frank Filas, EFR (ffilas@energyfuels.com)
Mike George, UDWQ (mmgeorge@utah.gov)

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M037-SanJuan/M0370012-Pandora/inspections/INSP-04152014.pdf



Mine: M/037/0012 Inspected: 04/15/2014






View into sealed portal

Security enclosure for portal




Utilities for site



Facility buildings









South end of waste rock pile

